

DOCUMENT NUMBER:	<b>MTN-0012-24</b>
ISSUE DATE:	<b>2024-04</b>

---

# MOTOROLA SOLUTIONS TECHNICAL NOTIFICATION (MTN)

## Obsolescence

---

### Title

UNC may push wrong configuration to a transport device and in result the NCM job will fail and cause critical network problems/failures.

### Technology

ASTRO® 25

### Symptoms

When pushing configurations to a group of transport devices (typically when configuration is pushed to multiple transport devices at the same time e.g. during system upgrade, system expansions), one of the devices may get the configuration destined for another device in the group. This may cause the device or a whole subnet to be disconnected from the network causing critical network problems/failures.

### Additional Information

This MTN was obsoleted on 04/05/2024. Please wait for a new revision of this MTN or official communication from MSI.

If you need more information on the reason for this obsolescence, please contact your MSI Technical support center.

[https://www.motorolasolutions.com/en\\_us/support.html](https://www.motorolasolutions.com/en_us/support.html)

### Labor Allowance

This is an informational bulletin. No labor warranty is implied, intended, or authorized

For assistance with this bulletin please contact your MSI Technical Support Centre at <https://motorolasolutions.com/support>

---

#### MOTOROLA SOLUTIONS TECHNICAL NOTIFICATION

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. © 2023 Motorola Solutions, Inc. All rights reserved.