

BELL SYSTEM PRACTICES
Plant Series

Appendix 1, Section 573-133-801, Issue 2
Teletypewriter Change Notice
TCN 1641 Issue 1
June, 1972
AT&T Co Standard
Classification: A1C
Billable to Telco: Yes X No

APPARATUS AFFECTED: 28 Electrical Service Units (LESU) Equipped With Either a TP151422, TP174001 or a TP178831 Receptacle Connector.
TP179426 Plate Assembly.

PART AFFECTED: None

REASON: To provide a warning label (100 W. MAX) near the receptacle connector.

CHANGE: A TP343470 label (100 W. MAX) is added and is to be affixed near the receptacle connector. (See SUPPLEMENTAL INFORMATION (1) .)

PUBLICATION AFFECTED: See SUPPLEMENTAL INFORMATION (2).

IDENTIFICATION: The TP343470 label (100 W. MAX) has red letters on a white background.

INTERCHANGEABILITY: Not affected. New part added.

PARTS AVAILABILITY: The TP343470 label is available.

SUPPLEMENTAL INFORMATION: (1) A1C - same as A1 except TELCO need only affix labels when making routine service call.

(2) The TP151422, TP174001 and TP178831 receptacle connectors and the TP179426 plate assembly are illustrated in the following Sections:

Section 573-133-800, Issue 2, Pages 3, 4, 5 and 6.
Section 573-133-801, Issue 2, Pages 2 and 8.
Section 573-133-802, Issue 3, Pages 3, 24 and 26.
Section 573-133-803, Issue 1, Page 2.
Section 573-133-804, Issue 2, Page 2.

REFERENCES: None

TCN INDEX CLASSIFICATION: 28 AE 01