

## **TP180930 BEARING**

*APPARATUS AFFECTED:* 33A, 33A-1, 33A-2, 33A-3, 33A-4, 33B, 33C, 33C-1, 33C-2, 33C-3, 33C-4, 33E, 33F, 33F-1, 33F-2, 33F-3, 33F-4 Teletypewriter-Sets.

*OBJECT:* To facilitate manufacture by providing an additional mounting hole in the bearing.

*CHANGE:* 1. An additional 6-40 tapped hole is being added to the TP180930 bearing in line with the existing 6-40 tapped hole.

2. The locating center for the two holes has been changed from 0.156 inch from the shoulder to 0.207 inch from the shoulder end of the bearing. The TP180930 bearing is shown in Teletype Bulletin 1184B, page 2-24, change 3.

*IDENTIFICATION:* New style bearings have two tapped holes; old style bearings have one tapped hole.

*INTERCHANGEABILITY:* New and old style bearings are interchangeable.

*CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:* This change is expected to be in effect by February, 1964.

*W.E.CO. STOCK OF OLD STYLE PARTS:* Old style parts may be furnished.

*APPLICATION TO APPARATUS IN THE FIELD:* There is no advantage in using new style parts.

*APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:* Units may be equipped with either new or old style parts.