

**TP183524 TURN BUTTON, TP183525 FLAT WASHER  
AND TP183526 RETAINING RING**

*APPARATUS AFFECTED:* 33A-1 through 33F-5 Teletypewriter-Sets; 35A and 35B Call Control Units.

*OBJECT:* To provide parts ordering information for the TP182688 switch assembly.

*CHANGE:* The following maintenance parts are added for the TP182688 switch assembly.

TP183524 Turn Button

TP183525 Flat Washer

TP183526 Retaining Ring

For location of switch, see Bulletin 1184B, page 3-5, change 3, and Bulletin 1187B, page 2-2, change 1, and page 2-6.

*IDENTIFICATION:* See "CHANGE".

*INTERCHANGEABILITY:* Not affected.

*CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:* Not affected.

*W.E.CO. STOCK OF OLD STYLE PARTS:* Not affected.

*APPLICATION TO APPARATUS IN THE FIELD:* Replacement parts may be used as required.

*APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:* Replacement parts may be used as required.