

## TP74700 SPRING

*APPARATUS AFFECTED:* All 33 Teletypewriter-Sets.

*OBJECT:* To provide more reliable operation of the function drive bail and to include a requirement which was omitted.

*CHANGE:* 1. The TP91120 spring which hooks between each of the two TP180769 and TP180770 links is replaced by a TP74700 spring.

2. Requirement is added to Teletype Bulletin 273B and Section 574-100-703 for the *Function Drive Bail Springs:*

With unit in its stop position

MIN. 4-1/2 pounds — MAX. 6-1/2 pounds to pull spring to its installed length. Parts are shown in Teletype Bulletin 1184, page 2-15, change 3.

*IDENTIFICATION:* The TP74700 spring has approximately 12 turns; the TP91120 spring has approximately 25 turns.

*INTERCHANGEABILITY:* New and old style springs are interchangeable.

*CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:* This change is now in effect.

*W.E.CO. STOCK OF OLD STYLE PARTS:* May be furnished for other applications.

*APPLICATION TO APPARATUS IN THE FIELD:* Old style springs giving satisfactory service need not be replaced.

*APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:* All units shall be equipped with new style parts.