IBM   INSTALLATION INSTRUCTIONS

Install FC 8007
Storage Column Installation
3583 Model L18/L36

Document Number 19P1501   EC H27554

SSD, Tucson

Written by:	D. Gormley
Checked by:	L. Curtis
Approved by:	
Support/DPCE Review by:	S. Moulton
Status:	Field Use

Note: This Field Feature Bill of Material (FFBM) must be installed only on the 3583 Model L18/L36 for which it is shipped.

PN 19P1501 1 of 5	EC H27554 16 NOV 00				

Before Installation (Sections 1 through 8)

1.0 Machines Affected

All 3583 Models L17/L36

2.0 Prerequisites / Concurrent / Companion

None

3.0 B/M To Be Installed

FFBM	Description
19P1409	Storage Column (FC 8007) and Instructions

4.0 Preparation

Read and understand the purpose and details of this installation instruction. Check all items and count parts listed on the B/M to be installed to determine that all parts have been received.

5.0 Programming Updates

None.

6.0 Purpose and Description

This FFBM provides a installation instructons to install a Storage column in a 3583 model L18/L36 library.

7.0 Installation Time

CE Hours	Machine Hours	System Hours	No Of CEs
1.0	0.5	0	1

8.0 Special Tools and/or Materials Required

Refer to Maintenance Information Manual for required tools.

PN 19P1501 3 of 5	EC H27554 16 NOV 00			

Installation (Step 10)

9.0 Safety

10.0 Details Of Installation

Note: Any parts that are removed during this change and not specified for reinstallation are to be set to the side for disposition as explained in Section 13.0.

10.1 Installing A Storage Column in 3583 Models L18/L36

— 1. Refer to 3583 Maintenance Information Manual,SA37-0425-00, IBM pn 35L1563, Chapter 10 when installing a Storage Column.

PN 19P1501	EC H27554				
4 of 5	16 NOV 00				

After Installation (Sections 11 through 14)

11.0 Field Updating

None.

12.0 Field Support Publications

None.

13.0 Parts Disposition

Any removed parts are the property of the customer.

14.0 Machine Records

__ 1. Using existing procedures, update all appropriate records to reflect that feature code 8007 as installed.

__ 2. Using existing procedures, report installation and quality.

PN 19P1501	EC H27554				
5 of 5	16 NOV 00				