

# HP 3PAR OS 3.1.3 MU2 Patch 13 Release Notes

This release notes document is for Patch 13 and intended for HP 3PAR Operating System Software 3.1.3.262 (MU2).

HP Part Number: QL226-98127  
Published: March 2015  
Edition: 1



© Copyright 2015 Hewlett-Packard Development Company, L.P.

Confidential computer software. Valid license from HP required for possession, use or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

### Acknowledgments

Intel®, Itanium®, Pentium®, Intel Inside®, and the Intel Inside logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Microsoft®, Windows®, Windows® XP, and Windows NT® are U.S. registered trademarks of Microsoft Corporation.

Adobe® and Acrobat® are trademarks of Adobe Systems Incorporated.

Java and Oracle are registered trademarks of Oracle and/or its affiliates.

UNIX® is a registered trademark of The Open Group.

### Documentation

For the latest version of this document, go to <http://www.hp.com/go/3par/>, navigate to your product page, click **Support for your product**, and then click **Manuals**.

---

# Contents

1 Overview of HP 3PAR OS.....	4
Supported Platforms.....	4
Patch Details.....	4
Included in This Patch.....	4
Affected components.....	5
Modifications to the HP 3PAR OS.....	5
Verifying the patch installation.....	5

---

# 1 Overview of HP 3PAR OS

This release notes document describes the modifications and known issues for Patch 13. This is only intended to be applied to HP 3PAR OS 3.1.3.262 (MU2). This is a recommended patch.

The installation of this patch affects the following packages:

- tpd-kernelpatch
- tpd-sysmgr
- tpd-libtpdapi
- tpd-api
- tpd-prerevert

## Supported Platforms

The HP 3PAR Configuration Matrix for HP 3PAR OS 3.1.3 contains information about supported hardware and software platforms. For additional information, see the Single Point of Connectivity Knowledge for HP Storage Products (SPOCK) website: <http://www.hp.com/storage/spock>.

## Patch Details

- Patch Name: HP 3PAR OS 3.1.3 MU2 P13
- Prerequisite: The Service Processor must be at release level SP-4.2.0.GA-29 + the latest available patch
- This patch applies to: HP 3PAR OS Release 3.1.3.262 (MU2)
- Obsoletes: None

---

**NOTE:** Applying this patch to the HP 3PAR OS might restart the affected OS components. With these restarts, events and alerts might be generated and this is an expected behavior. The system continues to serve data, but existing CLI or IMC sessions might be interrupted.

---

## Included in This Patch

HP 3PAR OS 3.1.3 MU2 P13 includes:

- Issue ID: 125084, 123814, 122458, 124442, 125444, 123987
- Description: Corrects Remote Copy, ODX (XCOPY Lite), CIM server and unexpected array restart issues.
- Affected Packages: tpd-kernelpatch, tpd-sysmgr, tpd-libtpdapi, tpd-api, tpd-prerevert
- Obsoletes: None
- Requires: OS-3.1.3.262-MU2
- Build Version: 3.1.3.272

---

**NOTE:** HP recommends installing patches in the same sequence as they are released, unless instructed otherwise.

---

## Affected components

Component	Version
System Manager	3.1.3.272 (P13)
TPD Kernel Patch	3.1.3.272 (P13)
CIM Server	3.1.3.272 (P13)

## Modifications to the HP 3PAR OS

This release addresses the following items:

Issue number	Description
122458	Corrects token processing for XCOPY Lite operations.
123814	Corrects Remote Copy structures after the upgrade.
123987	Corrects a condition where CIM server process grows over time and its high swap usage slows down other processes on the storage system.
124442	Corrects XCOPY Lite synchronization.
125084	Correct checkhealth issues for Remote Copy during node restart.
125444	Prevents a race condition during node down recovery which might cause an unexpected array restart.

## Verifying the patch installation

The installation of Patch 13 can be verified from an interactive CLI session. Issue the CLI command `showversion -a -b` to verify that Patch 13 is listed.

```
cli% showversion -a -b
Release version 3.1.3.262 (MU2)
Patches: P13

Component Name          Version
CLI Server              3.1.3.262 (MU2)
CLI Client              3.1.3.188
System Manager          3.1.3.272 (P13)
Kernel                  3.1.3.262 (MU2)
TPD Kernel Code         3.1.3.262 (MU2)
TPD Kernel Patch        3.1.3.272 (P13)
CIM Server              3.1.3.272 (P13)
.
.
.
```

**NOTE:** When displaying the `showversion` command output from the Service Processor, the CLI Client version is fixed in the SP code, and might differ from the output displayed on another system.