



# IBM INSTALLATION INSTRUCTIONS

## Install FC 8003, 8004 LVD or HVD Drive Installation 3583 Model L18/L36/72

Document Number 19P1500 EC H27554

SSD, Tucson

**Written by:** D. Gormley

**Checked by:** L. Curtis

**Approved by:**

**Support/DPCE Review by:** S. Moulton

**Status:** Field Use

**Note:** This Field Feature Bill of Material (FFBM) must be installed only on the 3583 Model L18/L36/L72 for which it is shipped.

PN 19P1500 1 of 5	EC H27554 16 NOV 00				
----------------------	------------------------	--	--	--	--

---

## Before Installation (Sections 1 through 8)

---

### 1.0 Machines Affected

All 3583 Models L17/L36/L72

---

### 2.0 Prerequisites / Concurrent / Companion

None

---

### 3.0 B/M To Be Installed

FFBM	Description
19P1406	LVD Drive Sled (FC 8003) and Instructions
19P1407	HVD Drive Sled (FC 8004) and Instructions

---

### 4.0 Preparation

Read and understand the purpose and details of this installation instruction. Check all items and count parts listed on the B/M to be installed to determine that all parts have been received.

## 5.0 Programming Updates

None.

## 6.0 Purpose and Description

This FFBM provides a Drive Sled Installation procedure for feature codes 8003 or 8004 in a 3583 library.

## 7.0 Installation Time

CE Hours	Machine Hours	System Hours	No Of CEs
1.0	0.5	0	1

## 8.0 Special Tools and/or Materials Required

Refer to Setup, Operator and Service guide for required tools.

PN 19P1500 3 of 5	EC H27554 16 NOV 00				
----------------------	------------------------	--	--	--	--

---

## Installation (Step 10)

---

### 9.0 Safety

---

### 10.0 Details Of Installation

**Note:** Any parts that are removed during this change and not specified for reinstallation are to be set to the side for disposition as explained in Section 13.0.

---

### 10.1 Installing A HVD or LVD Drive Sled in 3583 Models L18/L36/L72

1. Refer to 3583 maintenance Information Manual, SA37-0425-00, IBM pn 35L1563, Chapter 10 when installing A Drive Sled.

---

## After Installation (Sections 11 through 14)

---

### 11.0 Field Updating

None.

---

### 12.0 Field Support Publications

None.

---

### 13.0 Parts Disposition

Any removed parts are the property of the customer.

---

### 14.0 Machine Records

- 1. Using existing procedures, update all appropriate records to reflect that feature code 8003, 8004 as installed.
- 2. Using existing procedures, report installation and quality.