

IBM INSTALLATION INSTRUCTIONS

Install Modem Data Cable on 3584 Tape Library with Remote Support Feature

Document Number 19P4715 EC H28043A

SSD - Tucson

Written by: L. Kaja
Checked by: S. Latham
Approved by: T. Watssen
Support/DPCE Review by: L. Lawson
Status: Field Use

3584 L32	PN 19P4715 1 of 5	EC H28043A 08 OCT 2001				
-------------	----------------------	---------------------------	--	--	--	--

Before Installation (Sections 1 through 8)

1.0 Machines Affected

3584 Model L32 with Remote Support Feature (FC 2710) and without EC H28043A.

2.0 Prerequisite / Concurrent / Companion

2.1 Prerequisite

FC 2710 Remote Support Facility

2.2 Concurrent

None

3.0 FBM to be Installed

PN	Description
19P4692	Cable, 9-pin to 25-pin

4.0 Preparation

Read and understand the purpose and details of these installation instructions. Check all items listed on the Bill of Material to determine that all parts have been received.

5.0 Program Updates

None.

6.0 Purpose and Description

Provides a 50' 9-pin to 25-pin cable to connect between the modem (Remote Support Feature) and the MCP.

7.0 Installation Time

CE Hours	Machine Hours	System Hours
0.5	0.0	0.0

3584 L32	PN 19P4715 2 of 5	EC H28043A 08 OCT 2001				
-------------	----------------------	---------------------------	--	--	--	--

8.0 Special Tools and/or Materials Required

None.

Installation (Sections 9 through 12)

9.0 Safety

Attention

If the installation involves rework, remove all electrical power from the machine and any associated machines before beginning the installation. Observe normal safety precautions.

10.0 Details of Installation

- 1. Remove the 6 foot cable that is currently installed between the modem and the MCP connector J6.

- 2. Install cable PN 19P4692 (supplied) between the modem and MCP connector J6.

11.0 Test Procedure

None

12.0 Field Updating

None

After Installation (Sections 13 through 15)

13.0 Field Support Publications

None

14.0 Parts Disposition

All removed parts that are not required for re-installation are the property of the customer.

All parts furnished within the MES, and deemed not required for MES installation, are the property

of IBM and are to be transferred to the local branch for proper parts disposition.

15.0 Machine Records

- 1. Using existing procedures, update all field records to reflect that EC H28043A been installed.
- 2. Using existing procedures, report installation and quality.