

## 52-TYPE HEAD TELEPHONE SETS

### PIECE-PART DATA, REPLACEMENT PROCEDURES, AND MINOR REPAIRS

#### 1. GENERAL

**1.001** This addendum supplements Section 028-360-811, Issue 8 and is issued to include the P-23F410 Pad for use with the 15A Headband. The P-10E121 and the P-240421 pads will be rated Manufacture Discontinued.

#### 2. PIECE-PART DATA

The following changes apply to Part 2 of the section.

- (a) Page 4—Delete Note 3.
- (b) Fig. 1, Reference to 15A Headband—Change: (Includes P-10E121 Cushioned Pad) to (Includes P-23F410 Pad).

#### 3. REPLACEMENT PROCEDURES

The following changes apply to Part 3 of the section.

- (a) 3.01—revised. Add the 255 Tool (grooved pliers) to the *List of Tools and Materials*.
- (b) 3.47—revised.

**3.47 Cord fastener (plastic strap) Associated With 422A Plug:** To place a new P-17E761 cord fastener on the cord, proceed as follows: Secure the cord fastener to the cord with the P-360125 band as shown in Fig. 14A, using the 255 Tool (grooved pliers) or the long-nose pliers. Form the cord fastener by slipping the E end of the fastener through slot 3, as shown in Fig. 14B, and the F end through slots 1 and 2, as shown in Fig. 14C.