

**OUTGOING TRUNKS TO TRAFFIC SERVICE POSITION (TSP) OR TRAFFIC SERVICE
POSITION SYSTEM (TSPS) NO. 1
TESTS USING TRUNK TEST CIRCUIT SD-25918-01
NO. 5 CROSSBAR OFFICES**

1. GENERAL

1.001 This addendum supplements Section 218-289-501, Issue 7. Place this pink sheet ahead of Page 1 of the section.

1.002 This addendum is issued for the following reason:

- (a) To change a verification result.

This addendum does not affect Equipment Test Lists.

2. CHANGES TO SECTION

2.001 Test B, Step 16 and Step 17, Verification changed to read as follows:

STEP	ACTION	VERIFICATION
16	Restore TLK key.	If toll denial is provided— PK lamp remains extinguished. High tone silenced. If E and M supervision is provided— E lamp extinguished. At trunk circuit— E relay remains operated.
17	Restore ANS key.	OGT-CS lamp extinguished. In approximately 1 second— AS lamp extinguished If ETS provided— FT lamp extinguished. If testing SD-28062-01 and trunk is used for operator assistance without ANI— AS lamp remains lighted. If ETS provided— FT lamp remains lighted.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement