

6.7 VOLT CONVERTER POWER REMOVAL AND RESTORATION

NO. 2 ELECTRONIC SWITCHING SYSTEM

1. GENERAL

1.001 This addendum supplements Section 232-121-302, Issue 2. Place this pink sheet ahead of Page 1 of the section.

1.002 This addendum is being issued to correct two teletypewriter input message errors.

1.003 This addendum does not affect the Equipment Test List.

2. CHANGES TO SECTION

ISSUE 1 CHANGES

2.001 On Page 3, Step 13a, under the ACTION column, the last character in the input

message should be a zero. The step should appear as:

At TTY type in:
M TT:RMV:0!

2.002 On Page 5, Step 38, under the ACTION column, the input message presently reads M MC:RST! The step should appear as:

At TTY type in:
M CU:RST!

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement