

**CUSTOMER DIAL PULSE RECEIVER CIRCUIT**  
**(SD-2H114 AND SD-2H177)**

**TESTS**

**NO. 2 AND NO. 2B ELECTRONIC SWITCHING SYSTEMS**

**1. GENERAL**

**1.001** This addendum supplements Section 232-147-501, Issue 3. Place this pink sheet ahead of Page 1 of the section.

**1.002** This addendum is issued to include changes due to the EF-2 and 2B-EF-2 generic programs. This addendum does not affect the Equipment Test List.

**2. CHANGES TO SECTION**

**2.001** On Page 1, add the following paragraph:

**1.02.1** New (conventional) service order codes were adopted for use with the EF-2 and 2B-EF-2 generic programs. However, the translations can be configured with the old (No. 2 ESS unique) service order codes as an option. These old codes are common to all previous No. 2 and No. 2B ESS generic programs. The EF-2 and 2B-EF-2 generic programs can be arranged to recognize either option. In this section the term "conventional (new)" or "No. 2 ESS unique (old)" is used to identify the service order code for the keywords in each TTY input message given.

**2.002** On Page 2, paragraph 3.02, change the system response to read as follows:

*The system response for offices using No. 2 ESS unique (old) code is as follows:*

AR VY SVC aaa bbb  
TEN nn gcsl  
. .  
DSP ss rrbb

*The system response for offices using conventional (new) code is as follows:*

AR VY SVC aaa bbb  
OE nn gcsl  
. .  
DSP ss rrbb

**2.003** On Page 5, Step 7, for No. 2B ESS offices change ss = Number of trunk scanner in (0-11) from Step 3.02 to ss = Number of trunk scanner in decimal (00-11 for offices using the 2B-EF-1 generic program) or (00-30 for offices using 2B-EF-2 generic program) from 3.02.

**NOTICE**

Not for use or disclosure outside the  
Bell System except under written agreement