

SUBSCRIBER PLANT
TRANSMISSION INDEX
NOISE COMPONENT
SUMMARY PROCEDURES

1. GENERAL

1.01 This addendum is reissued to provide that Division Report E-5570A shall also be furnished the Supervisor of Corporate Books along with the Area Report E-5570A. Paragraphs below follow the numbering of the main section.

1.03.1 All Southwestern Company maintained wire centers shall be scheduled for survey once every two years.

2. NOISE DATA SUMMARY - FORM E-5569

2.02.1 A minimum of 190 measurements on working lines are required for each wire center surveyed, except for wire centers having less than 190 working lines. Wire centers which require less than 190 measurements shall be so indicated on schedules described in Section 301-320-500.

2.09 Division Plant Superintendents shall arrange to obtain a completed copy of Form E-5569 for each wire center scheduled during the calendar quarter. (A copy of Form E-5569 shall be furnished to the Division on a positive basis when a wire center is scheduled but not surveyed.)

2.10 A completed copy of Form SW-9252a, Central Office Noise Survey, shall accompany Form E-5569 for each wire center selected. The Division Plant Superintendent shall arrange for a review of the Central Office Noise Survey test results on Form SW-9252a. (See addendum 301-320-501SW)

3. PREPARATION OF INDICES - FORM E-5570

3.01.1 Southwestern Company maintained wire centers shall be selected for sampling and summarized on a Division basis.

3.03.1 Entries in Columns A and C of Division summaries shall be listed using the same nomenclature, sequence, and data for working lines as furnished on schedules in accordance with Addendum 301-320-500SW.

4. PREPARATION OF INDEX SUMMARY SHEET - E-5570A

4.01.1 Form E-5570A shall be used by the Division to combine their districts for a Division summary and by the Area to combine their Divisions for an Area summary.

6. REPORTS

6.01.1 Division summary reports on Form E-5570A shall be prepared for each calendar quarter report period and furnished to the General Plant Manager.

6.02.1 General Plant Managers shall arrange to forward one copy of each Division summary (E-5570A) and one copy of the Area summary (E-5570A) to reach the Supervisor of Corporate Books at Company Headquarters no later than the 10th of the month following the end of each calendar quarter. The Company summary, listing Area and Company results, shall be prepared by the Supervisor of Corporate Books and forwarded to New York. General Plant Managers shall arrange to furnish copies of their Area and Division reports to the Area Transmission Engineer as requested.