

E6 REPEATER ALIGNMENT PROCEDURE

1. GENERAL

1.001 This addendum supplements Section 332-206-200, Issue 2. Place this pink sheet ahead of page 1 of the section.

1.002 This addendum is issued for the following reasons:

(a) To clarify the example on page 6 in step 6 of the procedure **ADJUSTMENT OF THE 831-TYPE NETWORK (GAIN UNIT)**.

(b) To change an incorrect figure reference on page 19, step 6 of the procedure **830E NETWORK ADJUSTMENT**.

2. CHANGES TO SECTION

2.001 On page 6, the example in step 6 on the top half of the page should read:

Example: In the row corresponding to 12-dB gain, screws A, B, C, E, H, and 1, 2, 4, 5, 7, 9 are listed to be turned down. Tighten these firmly but not excessively, and leave all other screws raised. (Screw K is *not* to be turned down until step 15).

2.002 On page 19, step 6, the figure reference in the last sentence should be changed from Fig. 6 to Fig. 5.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement