

TP182719 GUIDE BRACKET

APPARATUS AFFECTED: All 33 Teletypewriter-Sets; 35A, 35B, 35C Call Control Units.

OBJECT: To provide designations for locating the TP182750 card (amplifier) and the TP182630 card (circuit).

CHANGE: The TP182719 guide bracket is modified by adding designations stenciled in 3/16 inch characters. The designations are located on the surface between the slot and the keyhole and are adjacent to the bend.

The TP182719 guide bracket is located in Teletype Bulletins 1184, page 3-6, original, and 1187B, page 2-3, change 1.

IDENTIFICATION: See "CHANGE".

INTERCHANGEABILITY: New and old style brackets are interchangeable.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: Old style parts shall not be furnished.

APPLICATION TO APPARATUS IN THE FIELD: Should be incorporated in all apparatus.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: All units shall be equipped with new style guide brackets.