

## **TP170201 SHAFT**

*APPARATUS AFFECTED:* 35A, 35B, 35C Perforator-Transmitter-Bases, 35A Typing Reperforator Unit and 35A and 35B Tape Typing Units.

*OBJECT:* To facilitate manufacture.

*CHANGE:* The left end of the TP170201 shaft has been reduced by 1/8 of an inch in length (Bulletin 1188B, page 2-4 and Bulletin 1187B, page 5-7).

*IDENTIFICATION:* See "CHANGE".

*INTERCHANGEABILITY:* New style and old style shafts are interchangeable.

*CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:* This change will be put into effect when present stocks are depleted. This is expected to be about the 4th quarter of 1963.

*W.E.CO. STOCK OF OLD STYLE PARTS:* May be furnished.

*APPLICATION TO APPARATUS IN THE FIELD:* There is no advantage in using the new style shaft.

*APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:* Units may be equipped with new or old style shafts.