

TP193755 MAGNET COIL COVER

APPARATUS AFFECTED: 35A Typing Reperforator Unit; 35A and 35B Tape Typing Units; TP193755 Magnet Coil Cover.

OBJECT: To eliminate a possible shock hazard.

CHANGE: The TP193755 magnet coil cover is changed to a 0.032-inch thick gray fiber with a 0.281-inch formed lip along the right and left sides. The old style cover is made of 0.062-inch thick polyethylene and has a 0.375-inch lip along two adjacent sides.

The TP193755 magnet coil cover is shown in Teletype Bulletin 1188B, page 2-10, original.

IDENTIFICATION: See "CHANGE".

INTERCHANGEABILITY: New style and old style covers are interchangeable.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change shall be incorporated as soon as manufacturing conditions permit. This is expected to be about January 1, 1965.

W.E.CO. STOCK OF OLD STYLE PARTS: Shall not be furnished after new style parts become available.

APPLICATION TO APPARATUS IN THE FIELD: Should be incorporated in all apparatus.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: All units shall be equipped with new style covers as soon as new style parts can be obtained from Teletype.