

TP162850 HANDLE

APPARATUS AFFECTED: 35A Typing Reperforator Unit; 35A, 35B Tape Typing Units; 35B, 35D Perforator-Transmitter-Bases; TP162850 Handle.

OBJECT: To facilitate manufacture.

CHANGE: The TP162850 handle is modified by adding a 6-40 tapped hole.

The TP162850 handle is shown in Teletype Bulletin 1188B, page 2-18, original.

IDENTIFICATION: See "CHANGE".

INTERCHANGEABILITY: New and old style handles are interchangeable.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: May be furnished.

APPLICATION TO APPARATUS IN THE FIELD: There is no advantage in using new style parts.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: Units may be equipped with new or old style parts.