

MAIN FRAME PROTECTION "B" TYPE FRAMES

1. GENERAL

1.001 This addendum supplements Section A302.001, Issue 8.

1.002 This addendum is reissued to add a note after Paragraph 1.05(c) and to revise Table 1 to identify the No. 29B and 30 protector blocks.

The following changes apply to Part 1 of the section:

(a) 1.05—Note added after subparagraph (c).←

*** Where the MDF protector mountings are connected to drainage coil assemblies, substitute No. 29B (.006 stamped on side) for No. 29 (unmarked) protector blocks; substitute No. 30 (blue color code on porcelain) for No. 27 (unmarked) protector blocks.

(b) Table 1—Footnote marked with triple asterisk (***) revised.

Note: Where the No. 377H transformer is used, use the No. 15 and 9 dummy protector blocks, respectively.

Add after paragraph 1.05(c).

Note: When the 121 type protector units are removed, the cable conductors may be automatically grounded. Therefore, before removing these protector units from circuits which have potential on the cable side (telegraph loops, carrier circuits, etc.,) the associated equipment should be taken out of service. It may be necessary to disconnect the equipment from the cable pair to prevent damage to the equipment. For this reason the modified B Test Clip with the M2EM cord is not recommended for use with the 121 type protector units.