

GENERAL INSTRUCTIONS

USE OF CORROSION RESISTANT

CR MATERIAL

NOTES CONCERNING THIS ADDENDUM

This addendum supplements Section G10.906 and is being issued to include an additional map of a highly corrosive location.

See addendum should be marked in Section G10.906 in the "contents," at Paragraphs 4.05(a), 4.09, 4.10, and following Paragraph 4.11 to indicate additional information has been added.

The following changes should be made in the "Contents:"

- Delete - Beacon C. O. Area
- Change - "Bayview" C. O. Area to "Academy"
- Change - "Broad" C. O. Area to "Terminal 4 - 5"
- Add - Coronado and Chula Vista (Palm City) Exchanges

4. MAPS

- 4.05(a) Change Beacon C. O. Area to read "Harbor."
- 4.09 Change Bayview C. O. Area to read "Academy."
- 4.10 Change Broad C. O. Area to read "Terminal 4 - 5."
- 4.12 See map on Page 2.

4.12 Coronado and Chula Vista (Palm City) Exchanges

