

## DIR-601 Firmware Release Notes

**Firmware: FW v1.02NA**

**Hardware: Rev.A1**

**Date: 2010/11/30**

### Problems Resolved:

1. SMTP server port should set 25 by default in email settings page.
2. DHCP lease time should set 1440 by default in network settings page.
3. Compliant with DNSSEC
4. Fix bug: Countdown string only lan change.
5. WPS feature which is moved to advanced page.
6. Change WEP KEY setting (from 4 keys to 1 key).
7. Fixed advanced dns description error on wan\_static.asp

### Enhancements:

None

### Know Issues:

None

----- END -----