

DIR-815 Firmware Release Notes

Firmware: FW v2.01

Hardware: Rev.B1

Date: 2012/07/24

Problems Resolved:

1. Fixed WLAN 5G MAC information issue in hidden page.
2. DS-lite does not connect automatically when user change IPv6 settings.
3. Add simple security option in IPv6 Firewall setting.
4. Fixed wrong status in wireless mode when STA connect to DUT with 802.11a.

Enhancements:

N/A

Note:

1. FW can not be backward compatible with A1 version.

----- END -----