



1995-1998 Honda Odyssey Upper Control Arm and Ball Joint Replacement

A video tutorial on how to change the upper control arm and or ball joint on a 1995-1998 Honda Odyssey.

Written By: eCuration



This document was generated on 2019-10-09 04:54:06 PM (MST).

INTRODUCTION

If you are experiencing front vibration, a wandering steering wheel or hearing a front clunking sound then it may be time to replace the front upper ball joints.

Follow this video guide from YouTuber [Oscar R.](#) to do the replacement yourself.

TOOLS:

- [Hydraulic Floor Jack](#) (1)
- [Jack Stand](#) (1)
- [Wheel Chocks](#) (1)
- [3/8" Drive Ratchet](#) (1)
- [10" Ratchet Extension](#) (1)
- [14mm Wrench](#) (1)
- [17 mm Box End Wrench](#) (1)
- [Hammer](#) (1)
- [Torque Wrench](#) (1)
- [Socket 17mm](#) (1)
- [14mm socket](#) (1)

PARTS:

- [Upper Ball Joint](#) (1)
- [Upper Control Arm](#) (1)

To reassemble your device, follow these instructions in reverse order.