

IBM CUSTOMER INSTALLATION INSTRUCTIONS

Install Feature Codes on SCSI System Cable for:
3580 Model H11/L11, H13/L13 or H23/L23
3581 Model H17/L17 or H13/L13
3583 Model L18/L36/L72.

Document Number 19P1424 EC H80250A

SSD, Tucson

Written by: D. Gormley
Updated by: C. Kovalik
Checked by: R. Roberts
Approved by: P. Webster
Support/DPCE Review by: S. Moulton
Status: Field Use

Note: This Field Feature Bill of Material (FFBM) must be installed only on the 3580 Model H11/L11, H13/L13 or H23/L23, 3581 Model H17/L17 or H13/L13, 3583 Model L18/L36/L72 for which it is shipped.

PN 19P1424 1 of 3	EC H27554 16 NOV 00	EC H80113 17 MAY 02	EC H80250A 17 DEC 02		
----------------------	------------------------	------------------------	-------------------------	--	--

Before Installation

1.0 Machines Affected

All 3580 Models H11/L11, H13/L13 or H23/L23 All 3581 Models H17/L17 or H13/L13 All 3583 Models L18/L36/L72

2.0 B/M To Be Installed

FFBM	Description
19P1386	0.4 Meter SCSI Cable (FC 5301) and Instructions
19P1387	2.5 Meter SCSI Cable (FC 5302) and Instructions
19P0939	0.72 Meter SCSI Cable (FC 5303) and instructions
19P1388	5 Meter SCSI Cable (FC 5305) and Instructions
19P1389	10 Meter SCSI Cable (FC 5310) and Instructions
19P1390	18 Meter SCSI Cable (FC 5318) and Instructions
19P1391	25 Meter SCSI Cable (FC 5325) and Instructions
19P1392	2.5 Meter SCSI Cable (FC 5602) and Instructions
19P1393	4.5 Meter SCSI Cable (FC 5604) and Instructions
19P1394	10 Meter SCSI Cable (FC 5610) and Instructions
19P1395	20 Meter SCSI Cable (FC 5620) and Instructions
19P1396	25 Meter SCSI Cable (FC 5625) and Instructions

3.0 Preparation

Read and understand the purpose and details of this installation instruction. Check all items and count parts listed on the B/M to be installed to determine that all parts have been received.

4.0 Purpose and Description

This FFBM provides a new SCSI interface cable for either host-to-device or drive-to-drive attachment.

5.0 Installation Time

Install Hours	Machine Hours	System Hours	No Of Persons
1.0	0.5	0	1

6.0 Special Tools and/or Materials Required

None.

PN 19P1424 2 of 3	EC H27554 16 NOV 00	EC H80113 17 MAY 02	EC H80250A 17 DEC 02		
----------------------	------------------------	------------------------	-------------------------	--	--

Installation

7.0 Details Of Installation

7.1 Installation of SCSI cables for 3580 Models H11/L11,

H13/L13 or H23/L23

When installing SCSI cables -

- ___ 1. For 3580 H11/L11, refer to 3580 Setup, Operator and Service guide GA32-0415-01, or higher, Chapter 2 or for 3580 H13/L13, refer to 3580 Setup, Operator and Service guide GA32-0456-00, or higher, Chapter 2 or for 3580 H23/L23 refer to 3580 Setup, Operator and Service guide GAxx-xxxx-xx, or higher, Chapter X.

7.2 Installation of SCSI Cables for 3581 Models H17/L17

- ___ 1. For 3581 H17/L17, refer to 3581 Setup, Operator and Service guide GA32-0412-01, or higher, Chapter 2 or for 3581 H13/L13 refer to 3581 Setup, Operator and Service guide GA32-0457-00, or higher Chapter 2 when installing SCSI cables.

7.3 Installation of SCSI cables for 3583 Models L18/L36/L72

- ___ 1. Refer to 3583 Setup, Operator, and Service guide, GA32-0411-03, or higher, Chapter 2 when installing SCSI cables.

PN 19P1424 3 of 3	EC H27554 16 NOV 00	EC H80113 17 MAY 02	EC H80250A 17 DEC 02		
----------------------	------------------------	------------------------	-------------------------	--	--