

CAROT 2/GENERIC 2
DATA BASE ADMINISTRATION
CENTRALIZED AUTOMATIC REPORTING ON TRUNKS (CAROT)

1. GENERAL

1.001 This addendum supplements Section 190-102-201, Issue 1. Place this pink sheet ahead of Page 1 of the section.

1.002 This addendum is being issued to provide changes and additions to Table C, Update Program—Phase 3 Error Codes. This addendum does not affect the Equipment Test List.

2. CHANGES TO SECTION

2.001 On Page 61/62, Table C, in the NNNNN VALUE FOR CODE = 000NN column, 14th entry from the top, change 00101 to 00001.

2.002 On Page 61/62, Table C, in the NNNNN VALUE FOR CODE = 000NN column, 15th entry from the top, change to read as follows: 00111 or 00110 or 00101.

2.003 On Page 61/62, Table C, in the CODE = NNNNN MEANING column, 15th entry from the top, change to read as follows: The trunk group record and/or facility record designated for the trunk(s) to be added does not exist in the data base.

2.004 On Page 61/62, Table C, in the CORRECTIVE ACTION column, 15th entry from the top, change to read as follows: Investigate trunk group and/or facility ID for a typographical error. If this is not the case, audit the data base to determine why the record designated for the trunk is not there.

2.005 On Page 61/62, Table C, for N VALUE FOR OPERATION = 0000N column, seventh entry from the top, add code 00010 which has the following meaning: The facility record designated for the trunk(s) to be added does not exist in the data base.

2.006 On Page 63/64, Table C, in the NNNNN VALUE FOR CODE = 000NN column, eighth entry from the top, change 00101 to 00001.

2.007 On Page 63/64, Table C, in the NNNNN VALUE FOR CODE = 000NN column, ninth entry from the top, change to read as follows: 00101 or 00110 or 00111.

2.008 On Page 63/64, Table C, in the CODE = NNNNN MEANING column, ninth entry from the top, change to read as follows: The test frame trunk group record and/or facility record for the test frame trunk(s) to be added does not exist in the data base.

2.009 On Page 63/64, Table C, in the CORRECTIVE ACTION column, ninth entry from the top, change to read as follows: Investigate test frame trunk group and/or facility record ID for typographical error. If this is not the case, audit the data base to determine why the record designated for the test frame trunks is not there.

2.010 On Page 63/64, Table C, for the N VALUE FOR OPERATION = 0000N column, fourth entry from the top, add code 00010 which has the following meaning: The facility record designated for the test frame trunk(s) to be added does not exist in the data base.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement