



**L MULTIPLEX TERMINALS  
COMMON EQUIPMENT  
GROUP CONNECTOR  
B2-TYPE—OUT-OF-SERVICE TESTS**

**1. GENERAL**

**1.001** This addendum supplements Section 356-020-503, Issue 3. The attached pages must be inserted in the section in accordance with the filing instructions above.

**1.002** This addendum is issued (a) to add information required to avoid STE interference with the 104.08-kHz pilot when the pilot is inserted locally and (b) to correct the labeling in Fig. 7.

**CHARTS 1 and 2**

The following changes apply to this section:

- (a) Step 13, Chart 1—revised
- (b) Step 12, Chart 2—revised
- (c) Fig. 7—revised

**Attached:**

**Page 7 dated August 1973, revised  
Page 8 dated August 1973, reissued  
Page 9 dated August 1973, reissued  
Page 10 dated August 1973, revised  
Page 15 dated August 1973, revised**