

## TP155614 COVER, TP311527 CLAMP AND TP125130 SCREW

*APPARATUS AFFECTED:* 28E, 28F, 28G, 28H, 28H-1, 28H-2, 28K, 28L, 28M, 28M-1, 28M-2, 28N, 2N-1, 2N-2, 28P, 28R, 28S, 28T, 28W, 28Y, 28AF, 28AK, 28AL and 28AM Typing Units; TP154741 Modification Kit; TP157260 Cable Assembly; and TP155614 Cover.

*OBJECT:* To provide a firmer anchor for the cable clamp associated with the TP155614 cover.

*CHANGE:* The TP155614 cover has been modified by eliminating the two slots in the 11/16-inch diameter hole and adding a slot, approximately 1/16 by 1/4 inch, to two sides of the cover to provide mounting facilities for a new mounting clamp.

The TP155766 cable clamp and two TP155723 screws associated with the old style TP155614 cover are replaced by a TP311527 cable clamp and two TP125130 screws.

The TP155614 cover, TP155766 cable clamp and TP155723 screws are shown in Bulletin 1149B, page 5-10, change 11; and Bulletin 1169B, page 5-35, change 8.

*IDENTIFICATION:* See "CHANGE". Also the end of the TP311527 cable clamp has a semicircle. The end of the TP155766 cable clamp is straight. The TP155723 screw is 4-48 x 1/2 inch. The TP125130 screw is 6-32 x 1/2 inch.

*INTERCHANGEABILITY:* Parts are not individually interchangeable.

*CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:* This change shall be incorporated as soon as manufacturing conditions permit. This is expected to be about May, 1965.

*W.E.CO. STOCK OF OLD STYLE PARTS:* The old style TP155614 cover and TP155766 cable clamp shall not be furnished after new style TP155614 cover and TP311527 clamp become available. The TP155723 screws may be used for other applications.

*APPLICATION TO APPARATUS IN THE FIELD:* Old style parts giving satisfactory service need not be replaced.

*APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:* Units may be equipped with new or old style parts. If parts involved require replacement or if parts are disassembled for other reasons, the new parts shall be incorporated.