

**ALTERNATE MOUNTING BRACKET
(FOR USE WITH ALL MODEL 213300, 213400,
OR 213500 DIGITAL ANNOUNCERS)**

INSTALLATION

GENERAL

1.01 Alternate mounting brackets for the Digital Announcer are described in this practice.

1.02 References

60-213400 Model 213400 Multi-Channel Digital Announcer Operation and Maintenance Manual

For additional information, contact:

Northern Telecom Inc.
Cook Electric Division
6201 Oakton Street
Morton Grove, Illinois 60053
Telephone (312)-967-6600
Telex 72-4472
TWX 910-223-3654
Cable "Cookpro"

INSTALLATION

2.01 Some production runs of Digital Announcers have the bracket attachment holes in different locations on the Control Processor and Multi-Channel chassis. This means that certain bracket positions will result in an offset between the two enclosures. Although this has no effect on Digital Announcer performance, some customers may object to the uneven appearance.

2.02 Alternate mounting brackets are packed with the standard brackets for each Digital Announcer. If the standard brackets do not permit proper chassis alignment, the alternate brackets should be used to achieve the correct spacing.

2.03 Figure 1 shows both standard and alternate bracket attachment.




Fig. 1 - Attachment of standard and alternate mounting brackets to Digital Announcer