

TROUBLE TICKETER FRAME
AUTOMATIC NUMBER IDENTIFICATION—TYPE B
EQUIPMENT DESIGN REQUIREMENTS
NO. 1 CROSSBAR, PANEL, AND STEP-BY-STEP SYSTEMS

1. GENERAL

1.001 This addendum supplements Sections 814-600-150, 815-408-150, and 816-206-150.

1.002 This addendum is issued:

(a) To change the equipment to make it usable when outpulsing of called number to an automatic intercept center is required.

(b) To provide equipment modifications that will enable the operation of calling line identification facilities with the trouble ticketer frame.

4. EQUIPMENT

The following changes apply to Part 4 of the section:

Under J93403A

Add: In List 1

Under SD-95816-01

TTKT Ckt
Fig. 4

WIRE	EQUIP
1	0

Under J93403K

Add:

List 9 — Apparatus and wiring per SD-95816-01, Fig. 4, required in addition to list 1 for use with calling line identification.

Under J93403L

Change: List 1

To Read:

List 1 — Equipment, assembly, and wiring per SD-95816-01, Fig. 1, for one trunk and number register unit (see 5.01 and Note A).

Add:

Note

A. Furnish ZI wiring only when operation with outpulsers arranged to outpulse called numbers to an automatic intercept center is required.

Bell Telephone Laboratories, Incorporated

Dept 5644

