

**500 AND 501-TYPE TELEPHONE SETS
INSTALLATION**

1. GENERAL

1.01 This addendum which supplements Section C32.537, issue 2, is issued to delete certain information contained in the section. This addendum should be retained with subsequent issues of the section until notice is given covering its cancellation or reissue.

1.02 Paragraphs 3.02 and 5.05 are rewritten and Figures 1 and 2 are to be disregarded insofar as they refer to bending the stop tab of the detent spring to allow the adjusting wheel to silence the ringer.

3. RINGER

3.02 Explain to the subscriber the operation of the wheel in the base of the set for controlling the ringer sound output as described in Part 5 — Tests.

5. TESTS

5.05 Disregard this paragraph.

Ringer cutoff by use of the adjusting wheel is not approved for use in this Area.