

DIR-615 Firmware Release Notes

Firmware: FW v5.11

Hardware: Rev.E3/E4

Date: 2011/04/21

Problems Resolved:

1. Wireless can't connect to DCS-5220 when using WPA-PSK encryption.

Enhancements:

1. Support 12-24 in schedule function.
2. Change WEP KEY setting (from 4 keys to 1 key).
3. Support IPv6 DS-Lite and Display IPv6 Routing Table.
4. Add Seoul to time zone selection.

Note:

----- END -----